Java SE vulnerability in Belden/Hirschmann software products

Date: 2023-07-14
Version: 1.0

Summary

The following vulnerabilities could affect the functionality in one or more versions of the products listed in the next section:

ID	Title / Description	Severity
CVE-2023-21930[1]	Java SE vulnerability	CVSS v3.1: 7.4

Affected Products

Brand	Product Line / Platform	Product	Version
Belden	Provize	Basic	01.1.04 or lower
Belden	Provize	Suite	01.3.00 or lower
Hirschmann	Network Management	Industrial HiVision	08.3.02 or lower
Hirschmann	Network Management	HiFusion	04.3.02 or lower
Hirschmann	Network Management	HiView	04.2.02 or lower

Solution

Updates are available, which address the vulnerability. Customers are advised to update their product.

Brand	Product Line / Platform	Product	Version
Belden	Provize	Basic	01.1.05
Belden	Provize	Suite	01.4.00
Hirschmann	Network Management	Industrial HiVision	08.3.03
Hirschmann	Network Management	HiFusion	04.3.03
Hirschmann	Network Management	HiView	04.2.03

For Help or Feedback

To view all Belden Security Bulletins or to report suspected security vulnerabilities, go to https://www.belden.com/security.
For technical support and other requests, please visit https://hirschmann-support.belden.com

Related Links

- [1] https://nvd.nist.gov/vuln/detail/CVE-2023-21930

Disclaimer

THE SECURITY BULLETIN, AND INFORMATION CONTAINED HEREIN, ARE PROVIDED ON AN "AS IS" BASIS AND DO NOT IMPLY ANY KIND OF GUARANTEE OR WARRANTY, INCLUDING THE WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE. YOUR USE OF THE BULLETIN, AND INFORMATION CONTAINED HEREIN, OR MATERIALS LINKED FROM THE BULLETIN, IS AT YOUR OWN RISK. INFORMATION IN THIS BULLETIN AND ANY RELATED COMMUNICATIONS IS BASED ON OUR KNOWLEDGE AT THE TIME OF PUBLICATION AND IS SUBJECT TO CHANGE WITHOUT NOTICE. BELDEN RESERVES THE RIGHT TO CHANGE OR UPDATE BULLETINS AT ANY TIME.

Revisions

V1.0 (2023-07-14)   Bulletin created.