18th November 2025

Product Change Notice – 5G Modem Firmware Update to Version 45.00.136

Summary

The firmware version 45.00.136 for Telit FN990 5G modem series has been released by Telit. NetModule has qualified the new firmware for use with NetModule products.

- 5.0.0.101 or higher

NetModule recommends updating the Telit FN990 5G modem to firmware version 45.00.136

Affected Products

All products with product options "-N" for 5G rel. 16 based on Telit FN990 modem are affected. Products using other cellular products options: e.g. "Lp", "L"

Product Change:

The following enhancements have been introduced with firmware version 45.00.136

+Various enhancements in cybersecurity
+Various GNSS enhancements
+Mobile Network Operators support improvements
+Various Bug fixing

Additional Information

The firmware image is available for download here:

— Telit FN990 for worldwide region, order code N:
https://share.netmodule.com/public/system-software/firmware/FN990A28-HP_45.00.135_CUST_5695_r2.tgz

Thank you very much for your trust in our company and if you have any questions, please do not hesitate to contact your local Belden sales representative belden.com/support/contact-us or NetModule support at netmodule.support@belden.com or by phone our Frankfurt office P. +49 6196 779979 0 / Bern office P. +41 31 985 25 10