Belden Security Bulletin – Industrial IT BSECV-2022-20

TinyXML vulnerability in Hirschmann HiLCOS products

Date: 2022-11-23 Version: 1.0

Summary

The following vulnerability could affect the functionality in one or more versions of the products listed in the next section:

ID	Title / Description	Severity
CVE-2021-42260 ¹	TinyXML through 2.6.2 has an infinite loop in	CVSS v3.1: 7.5
	TiXmlParsingData::Stamp in tinyxmlparser.cpp via the	
	TIXML_UTF_LEAD_0 case. It can be triggered by a	
	crafted XML message and leads to a denial of service	

Affected Products

Brand	Product Line / Platform	Product	Version
Hirschmann	HiLCOS	OpenBAT, WLC,	8.60 or higher
		BAT450, BAT867,	
		BATOne, BAT-	
		Controler Virtual	

Solution

Updates are available, which address the vulnerability. Customers are advised to update their product.

Brand	Product Line / Platform	Product	Version
Hirschmann	HiLCOS	OpenBAT, WLC,	10.34-RU3
		BAT450, BAT867,	10.12-RU10
		BATone, BAT-	
		Controller Virtual	

For Help or Feedback

To view all Belden Security Bulletins or to report suspected security vulnerabilities, go to https://www.belden.com/security.

For technical support and other requests, please visit https://hirschmann-support.belden.com

Related Links

• [1] https://nvd.nist.gov/vuln/detail/CVE-2021-42260

Disclaimer

THE SECURITY BULLETIN, AND INFORMATION CONTAINED HEREIN, ARE PROVIDED ON AN "AS IS" BASIS AND DO NOT IMPLY ANY KIND OF GUARANTEE OR WARRANTY, INCLUDING THE WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR USE. YOUR USE OF THE BULLETIN, AND INFORMATION CONTAINED HEREIN, OR MATERIALS LINKED FROM THE BULLETIN, IS AT YOUR OWN RISK. INFORMATION IN THIS BULLETIN AND ANY RELATED COMMUNICATIONS IS BASED ON OUR KNOWLEDGE AT THE TIME OF PUBLICATION AND IS SUBJECT TO CHANGE WITHOUT NOTICE. BELDEN RESERVES THE RIGHT TO CHANGE OR UPDATE BULLETINS AT ANY TIME.

Revisions

V1.0 (2022-11-23): Bulletin created.